



243442

000006

## Conversation Record

Incoming telephone January 10, 1990 8:45am

Contact: Scott Moyer IEPA 217-782-3335Subject: IPC Site (Rockford, IL) --Possible Removal Action

Summary: He said that he has gotten the results for the analyses of the samples that were taken from the underground tanks and the aboveground tank at the site. These were split samples that were obtained when IPC sampled these tanks.

Under Subtitle G of the State regulations, the results showed that at least some of the materials sampled are hazardous materials because of the flash points. He is going to send me a copy of the results.

There are four underground tanks at the site and one aboveground tank. Some or all of the underground tanks may be interconnected, he does not know for sure. He has to look at the results further to see how much of the materials at the site might be hazardous.

He suggested that possibly an immediate removal might be required that the USEPA might undertake. This would show that the USEPA is also interested in the site. He has not yet talked with IPC to see if they have any plans for addressing the situation.

Removal of these materials would be desirable. It would not be desirable to leave this material at the site until a remedial action might be undertaken in 2 or 3 years. A removal at this time may or may not include the removal of one or more of the tanks. The condition of the underground tanks is not known.

If IPC were to do this removal and the site were not on the NPL, they would have to obtain a closure permit from the State.

One of the samples also showed 3.4 ppm mercury.

Action required: Decide what action USEPA should take.

Prepared by: Bernard J. Schorle

J.S.

cc: J.Barnette/L.Zintak EERB, WMD

K.Peaceman, ORC

K.Street, RERB, WMD